UNCLASSIFIED

AD NUMBER

AD367483

CLASSIFICATION CHANGES

TO: unclassified

FROM: confidential

LIMITATION CHANGES

TO:

Approved for public release, distribution unlimited


FROM:

Distribution: USGO: others to Director, Defense Atomic Support Agency, Washington, D. C. 20301.

AUTHORITY

DSWA ltr., 18 Apr 1997; DSWA ltr., 18 Apr 1997

THIS PAGE IS UNCLASSIFIED



BUREAU OF SHIPS GROUP TECHNICAL INSPECTION REPORT

Classification (Canadiad) (Changed to CONFIDENTIAL,


By Authority of Local Chieff of State Action of 12 April 1474

By Authority of Local Chieff of State Action of 12 April 1474

By Affice State Action of 12 April 1474

LE COVERNMENT AGENCIES MAY OBTAIN COPIES OF THIS REPORT DIRECTLY FROM DDC. OTHER QUALIFIED DDC USERS SHALL REQUEST THROUGH

Director
Defense Atomic Support Agency
Washington 7. 20202






TABLE OF CONTENTS:

	PAGE NO.
Ship Characteristics Sheet	3
Midship Section	4
Overall Summary of Damage;	5
Hull Technical Inspection Report (Section I)	11
Machinery Technical Inspection Report (Section II)	16
Electrical Technical Inspection Report (Section III)	22
Photographic Section (Section IV)	28
Commanding Officers Report (Appendix)	31

SECRET

U.S.S. CORTLAND (APA75)

Page 2 of 33 Pages

U.S.S. CORTLAND (APA 75)

SHIP CHARACTERISTICS

Building Yard: Consolidated Steel Corp.; Wilmington,

California.

Commissioned: 1 January 1945.

HULL

Length Overall: 426 feet 0 inches.

Length on Waterline: 400 feet 0 inches.

Beam (extreme): 58 feet 0 inches.

Depth (molded to upper deck): 37 feet 0 inches.

Drafts at time of test: Fwd. 8 feet 9 inches.

Aft. 18 feet 8 inches.

Limiting displacement: 7,080 tons.

Displacement at time of test: 5,984 tons.

MAIN PROPULSION PLANT

Main Engines: Two sets of Westinghouse steam turbines, directly connected to Westinghouse main gen-

erators. Two main shaft motors.

Main Condensers: Two are installed in ship.

Boilers: Two Babcock and Wilcox boilers are in-

stalled in ship. 450 psi gauge - 750° F.

Propellers: Two are installed in ship.

Main Shafts: Two are installed in ship.

Ships Service Generators: Five are installed in

ship.

Two - 250 KW. - 450 V. - A.C.


One - 150 KW. - 450 V. - A.C.

Two - 100 KW. - 120/240 V. - D.C.

SECRET

USS CORTLAND (APA75)

Page ? of 33 Pages



MIDSHIP

SECTION

TEST B

U.S.S. CORTLAND (APA 75)

SECRET

PAGE 4 OF 33

7427

TECHNICAL INSPECTION REPORT

OVERALL SUMMARY

- I. Target Condition after Test.
 - (a) Drafts after test; general areas of flooding, sources.

 There was no flooding, hence no change in drafts or list.
 - (b) Structural damage.

HULL

None.

MACHINERY

No comment.

ELECTRICAL

No structural damage was observed which affected electrical equipment.

(c) Other damage.

HULL

No comment.

MACHINERY

There was no damage to machinery of this vessel during Test B.

SECRET

U.S.S. CORTLAND (APA75)

Page 5 of 33 Pages

ELECTRICAL

No electrical damage occurred as a result of Test B.

- II. Forces Evidenced and Effects Noted.
 - (a) Heat

HULL

None.

MACHINERY

No evidence.

ELECTRICAL

There was no evidence of heat.

(b) Fires and explosions.

HULL

None.

MACHINERY

No evidence.

ELECTRICAL

There was no evidence of fires or explosions.

(c) Shock.

HULL

None.

SECRET

U.S.S. CORTLAND (APA75)

Page 6 of 33 Pages

MACHINERY

No evidence.

ELECTRICAL

There was no evidence of shock on electrical equipment.

(d) Pressure.

HULL

None.

MACHI NERY

No evidence.

ELECTRICAL

There was no evidence of pressure on electrical equipment.

(e) Effects apparently peculiar to the Atom Bomb.

HULL

None.

MACHINERY

None.

ELECTRICAL

There were no effects noted that are considered peculiar to the Atomic Bomb other than radioactivity.

JECRET

U.S.S. CORTLAND (APA75)

Page 7 of 33 Pages

- III. Results of Test on Target.
 - (a) Effect on machinery, electrical, and ship control.

HULL

Not observed.

MACHINERY

None.

ELECTRICAL

All electrical equipment was operable and ships control was unaffected.

(b) Effect on gunnery and fire control.

HULL

Not observed.

MACHINERY

No comment

ELECTRICAL

Gunnery and fire control were unaffected electrically.

(c) Effect on watertight integrity and stability.

HULL

None.

MACHINERY

No comment.

SECRET

U.S.F CORTLAND (APA75)

Page 8 of 33 Pages

ELECTRICÁL

None.

(a) Effect on personnel and habitability.

HULL

None.

MACHINERY

None.

ELECTRICAL

It is considered the only effect on personnel and habitability would have been that due to radioactivity. The extent of such effects are unknown.

(e) Effect on fighting efficiency.

HULL

None.

MACHINERY

None.

ELECTRICAL

There was no effect on the fighting efficiency of this vessel as a result of Test B from electrical failures. It is considered that, except for possible personnel casualties due to radioactivity, this vessel's fighting efficiency would have been unimpaired.

SECRET

U.S.S. CORTLAND (APA75)

Page 9 of 33 Pages

IV. General Summary of Observers' Impressions and Conclusions.

HULL

No comment.

MACHINERY

The CORTLAND was cutside the effective range of the explosion of Test B.

ELECTRICAL

The distance of this vessel from the blast was too great for electrical damage to occur.

V. Any Preliminary, General, or Specific Recommendation of the Inspection Group.

HULL

Although this ship was located on the outer fringe of the target array, hatch boards on #2 cargo hatch were dislodged. It is indicated that a more adequate method of securing these boards is required.

MACHINERY

None.

ELECTRICAL

None.

SECRET

U.S.S. CORTLAND (APA75)

Page 10 of 33 Pages

TECHNICAL INSPECTION REPORT SECTION I - HULL

GENERAL SUMMARY OF HULL DAMAGE

- L. Target Condition After Test.
- (a) Drafts after test; list; general areas of flooding, sources.

 There was no flooding, hence no change in drafts or list.
 - (b) Structural damage.

None.

(c) Other damage.

Not observed.

- IL Forces Evidenced and Effects Noted.
 - (a) Heat.

None.

(b) Fires and explosions.

None.

(c) Shock.

None.

(d) Pressure.

None.

(e) Effects apparently peculiar to the atom bomb.

None.

SECRET

USS CORTLAND (APA75)

Page 11 of 33 Pages

III. Effects of Damage.

(a) Effect on machinery, electrical, and ship control.

Not observed.

(b) Effect on gunnery and fire control.

Not observed.

(c) Effect on water-tight integrity and stability.

None.

(d) Effect on personnel and habitability.

None.

(e) Effect on fighting efficiency.

None.

IV. General Summary.

SECRET

No comment.

V. Preliminary Recommendations.

Although this ship was located on the outer fringe of the target array, hatch boards on #2 cargo hatch were dislodged. It is indicated that a more adequate method of securing these boards is required.

VI. Instructions of loading the vessel specified the following:

ITEM	LOADING
Fuel Oil	95%
D ies el Oil	95%
Ammunition	100%
Potable and reserve feed water	95%
Salt water ballast	None
	USS CORTLAND (APA75)

Page 12 of 33 Pages

Details of the actual quantities of the various items aboard are included in Report No. 7, Stability Inspection Report, submitted by the ship's force in accordance with "Instructions to Target Vessels for Tests and Observations by Ships Force" issued by the Director of Ships Material. This report is available for inspection in the Bureau of Ships Crossroads Files.

SECRET.

USS CORTLAND (APA75)

Page 13 of 33 Pages

DETAILED DESCRIPTION OF HULL DAMAGE

A. General Description of Hull Damage.

None. Photographs Pages 29 and 30 show general views of the exterior of the ship after rest B.

B. Superstructure.

No damage.

C. Turrets, Guns and Directors.

No damage.

D. Torpedo Mounts, Depth Charge Gear.

Not Applicable.

E. Weather Deck.

Two hatchboards on #2 cargo hatch were dislodged. No deflection was recorded on any of the scratch gages installed between the main and upper decks. A deck survey revealed no change in the deck.

F. Exterior Hull.

No damage

G. Interior Compartments (above w.l.).

No damage.

H. Armor Decks and Miscellaneous Armor.

Not Applicable.

I. Interior Compartments (below w.l.).

No damage.

SECRET

USS CORTLAND (APA75)

Page 14 of 33 Pages

J. Underwater Hull.

No damage.

K. Tanks.

No damage,

L. Flooding.

None.

M. Ventilation.

No damage.

N. Ship Control.

No damage.

O. Fire Control.

No damage.

P. Ammunition Behavior.

No damage.

Q. Ammunition Handling.

No damage.

R. Strength.

No damage.

S. Miscellaneous.

No comment.

T. Coverings.

No damage.

SECRET

USS CORTLAND (APA75)

Page 15 of 33 Pages

TECHNICAL INSPECTION REPORT

SECTION II - MACHINERY

GENERAL SUMMARY OF MACHINERY DAMAGE

- I. Target Condition After Test.
- (a) Drafts after test; list; general areas of flooding, sources.

No data taken by machinery group.

(b) Structural damage.

No comment.

(c) Other damage.

There was no damage to machinery of this vessel during Test B.

- II. Forces Evidenced and Effects Noted.
 - (a) Heat.

No evidence.

(b) Fires and explosions.

No evidence.

(c) Shock.

No evidence.

(d) Pressure.

No evidence.

SECRET

USS CORTLAND (APA-75)

Page 16 of 33 Pages

DETAILED DESCRIPTION OF MACHINERY DAMAGE

- A. General Description of Machinery Damage.
 - (a) Overall condition.

The overall condition of the machinery was not changed by Test B.

(b) Areas of major damage.

None.

(c) Primary causes of damage.

None.

(d) Effect of target test on overall operation of machinery plant.

The overall operation of the machinery plant remained unchanged as a result of Test B. Full operation was resumed immediately after the Test.

B. Boilers.

No damage. Both boilers were steamed after Test B. Performance was normal. Hydrostatic tests indicate no change in the tightness of the boilers.

HYDROSTATIC TEST ON BOILER #1

Before Test B. After Test B.

Initial Pressure 450 lb./sq. in. 450 lb./sq. in.

Time required for pressure to drop

SECRET USS CORTLAND (APA-75)

Page 18 of 33 Pages

100 lbs.	4 minutes	5 minutes
200 lbs.	6 minutes	8 minutes
300 lbs.	9 minutes	11 minutes
400 lbs.	15 minutes	18 minutes
onnad to 0	9 1/9 houng	2 hours

Pressure dropped to 0

2 1/2 hours

3 hours

C. Blowers.

No damage. All four blowers were operated under service conditions after Test B.

D. Fuel Oil Equipment.

No damage. All fuel oil equipment was operated incident to operating the boilers.

Boiler Feedwater Equipment. E.

No damage. All boiler feedwater equipment was operated satisfactorily incident to operating the boilers.

F. Main Engines.

No damage. Both main engines were operated after Test B. Performance was normal.

G. Reduction Gears.

Not applicable.

H. Shafting and Bearings.

No damage. Both shafts were operated under power after Test B, and operation was normal.

I. Lubrication System.

No damage. The lubrication system was operated incident to operation of the main engines.

SECRET

USS CORTLAND (APA-75)

Page 19 of 33 Pages

J. Condensers and Air Ejectors.

No damage. The after condenser, on which the suction and overboard discharge were left open, also the forward condenser were operated under power and normal vacuum obtained.

K. Pumps.

No damage. All pumps were operated under power at rated pressure and normal operation was obtained.

L. Auxiliary Generators (Turbines and Gears).

No damage. All turbo-generators were operated under service conditions. Performance was normal.

M. Propellers.

No damage. The propellers functioned normally with the main engines in use.

N. Distilling Plant.

Undamaged. The distilling plant was placed in service after the test, and functioned normally

O. Refrigerating Plant.

No damage. The refrigerating plant was placed in service after the test, and functioned normally.

P. Winches, Windlasses and Capstans.

No damage. All equipment was operated under service conditions, and functioned normally.

Q. Steering Engine.

Undamaged. The steering equipment was operated under service conditions after Test B, and functioned normally.

SECRET

USS CORTLAND (APA-75)

Page 20 of 33 Pages

R. Elevators, Ammunition Hoists, Etc.

No damage. All ammunition hoists and gasoline hoist were operated by power after Test B, and functioned normally.

S. Ventilation (Machinery).

No damage. All ventilation machinery was operated after the test, and functioned normally.

T. Air Compressors.

No damage. The air compressor was operated by power and is in normal condition.

U. Diesels (Generators and Boats).

No damage. The diesel generator and diesel fire pump were operated under service conditions after Test B, and functioned normally.

V. Piping.

No damage. All piping was used at normal operating pressures, and no defects were found.

W. Miscellaneous.

No damage. All miscellaneous equipment has been operated since Test B, and functions normally.

USS CORTLAND (APA-75)

SECRET

Page 21 of 33 Pages

TECHNICAL INSPECTION REPORT

SECTION III - ELECTRICAL

GENERAL SUMMARY OF ELECTRICAL DAMAGE

- I. Target Condition After Test.
 - (a) Drafts after test, list, general areas of flooding, sources.

 Drafts or list were not observed. There was no flooding.
 - (b) Structural damage.

No structural damage was observed which affected electrical equipment.

(c) Damage.

No electrical damage occurred as a result of test B.

- II. Forces Evidenced and Effects Noted.
 - (a) Heat.

There was no evidence of heat.

(b) Fires and explosions.

There was no evidence of fires or explosions.

(c) Shock.

There was no evidence of shock on electrical equipment.

(d) Pressure.

There was no evidence of pressure on electrical equipment.

SECRET

U.S.S. CORTLAND (APA75)

Page 22 of 33 Pages

(e) Any effects peculiar to the atomic bomb.

There were no effects noted that are considered peculiar to the atomic bomb other than radioactivity.

- III. Effects of Damage.
 - (a) Effect on electrical equipment and ship control.

All electrical equipment was operable and ships control was unaffected.

- (b) Effect on gunnery and fire control.

 Gunnery and fire control were unaffected electrically.
- (c) Effect on water-tight integrity and stability.

 None.
- (d) Effect on personnel and habitability.

It is considered the only effect on personnel and habitability would have been that due to radioactivity. The extent of such effects are unknown.

(e) Total effect on fighting efficiency.

There was no effect on the fighting efficiency of this vessel as a result of test B from electrical failures. It is considered that, except for possible personnel casualties due to radioactivity, this vessel's fighting efficiency would have been unimpaired.

IV. General Summary of Observer's Impressions and Conclusions.

The distance of this vessel from the blast was too great for electrical damage to occur.

SECRET

U.S.S. CORTLAND (APA75)

V. Any Preliminary, General, or Specific Recommencations of the Inspection Group.

None.

SECRET

U.S.S. CORTLAND (APA75)

Page 24 of 33 Pages

DETAILED DESCRIPTION OF ELECTRICAL DAMAGE

- A. General Description of Electrical Damage.
 - (a) Overall condition.

This vessel received no damage as a result of test B to electrical equipment.

(b) Areas of major damage.

None.

- (c) Primary causes of damage in each area of major damage.
 - There was no electrical damage.
- (d) The effects of the target test on the overall operation of the electric plant.

All electrical equipment was tested and found to be operable.

(e) Types of equipment most effected.

None.

B. Electric Propulsion Rotating Equipment (S41).

No damage.

C. Electric Propulsion Control Equipment (S41).

No damage.

D. Ship's Service Generators (S61).

No damage.

SECRET

U.S.S. CORTLAND (APA75)

Page 25 of 33 Pages

E. Emergency Generators (S61).

No damage was observed. The emergency generator was operating during the test and supplying power to the NMC Fathometer which continued to operate at least 2 minutes after Zero time.

F. Switchboands and Distribution Panels (S62).

No damage.

G. Wiring, Wiring Equipment, and Wireways (S62).

No damage.

H. Transformers (S62).

No damage.

I. Submarine Propelling Batteries (S62).

Not applicable.

J. Portable Batteries (S62).

No damage.

K. Motors, Motor-Generator Sets and Motor Controllers (S63).

No damage.

L. Lighting Equipment (S64).

No damage.

M. Searchlights (S66).

No damage.

SECRET

U.S.S. CORTLAND (APA75)

Page 26 of 33 Pages

N. Degaussing Equipment (S81).

No damage.

O. Gyro Compass Equipment (S24).

No damage.

P. Sound Powered Telephones. (S65).

No damage.

Q. Ship's Service Telephones (S65)Not applicable.

R. Announcing Systems (S65).

No damage.

S. Telegraphs (S65).

No damage.

T. Indicating Systems (S65).

No damage.

U. I.C. and A.C.O. Switchboards (SC5).

No damage.

V. F.C. Switchboards (S71).

No damage.

SECRET

U.S.S. CORTLAND (APA75)

SECTION IV


PHOTOGRAPHS

TEST BAKER

SECRET

U.S.S. CORTLAND (APA75)

Page 28 of 33 Pages



AA-CR-227-283-117. Starboard bow after Test B.

SECRET

USS CORTLAND (APA75)

Page 29 of 33 Pages

7427



AA-CR-227-283-113. Port quarter after Test B.

SECRET

USS CORTLAND (APA75)

Page 30 of 33 Pages

7427

APPENDIX

COMMANDING OFFICERS REPORT

TEST BAKER

SECRET

U.S.S. CORTLAND (APA75)

Page 31 of 33 Pages

REPORT #11

COMMANDING OFFICERS REPORT

SECTION I

The U.S.S. CORTLAND (APA 75) is of the GILLIAM type and was located in the extreme western edge of the target array, 3750 yards bearing 247° true from the center.

At the time of the test the ship was in fair material condition and completely sealed up, except for the emergency Diesel Generator. This generator was running and the vent used to supply it with required air was left open.

SECRET

U.S.S. CORTLAND (APA75)

Page 32 of 33 Pages

COMFIDENTIAL

SEC'TION II


PART A - GENERAL SUMMARY

- I. The drafts before and after the test were the same; there was no structural damage; there was no change in the operability of machinery. The temperature of the ship was normal and it is estimated that there would have been no personnel casualties.
- II. (a) There was no evidence of heat.
 - (b) There were no fires or explosions.
- (c) The only evidence of shock was the dislodging of two metal pontoons over number two hatch.
 - (d) There was no evidence of pressure.
- (e) The ship was slightly over tolerance in radioactivity in certain areas. These areas were all located near the skin of the ship next to the water line. These readings were taken Baker Day plus five (5).
- III. There were no effects on:
 - (a) Propulsion and Ship control.
 - (b) Gunnery and Fire Control.
 - (c) Water-tight Integrity and Stability.
 - (d) Personnel and habitability.
 - (e) Fighting efficiency.
- IV. It is believed that the bomb had oracically no effect on this ship.
- V. There are no recommendations.



U.S.S. CORTLAND (AF 175)

Page 33 of 33 Pages



anged to CONFIDENTIA

CONFIDENTIAL



Defense Special Weapons Agency 6801 Telegraph Road Alexandria, Virginia 22310-3398

TRC

18 April 1997

MEMORANDUM FOR DEFENSE TECHNICAL INFORMATION CENTER ATTENTION: OMI/Mr. William Bush (Security)

SUBJECT: Declassification of Reports

The Defense Special Weapons Agency has declassified the following reports:

✓AD-366588 4	XRD-203-Section 12 🗸
AD-366589	XRD-200-Section 9
AD-366590 ►	XRD-204-Section 13
AD-366591►	XRD-183
✓ AD-366586 ★	XRD-201-Section 10
►AD-367487.	XRD-131-Volume 2-
✓AD-367516¥	XRD- ₹ 143 ~
✓AD-367493 ८	XRD-142 ►
AD-801410L ✔	XRD-138
AD-376831L 🗸	XRD-83
AD-366759 ►	XRD-80
✓AD-376830L ❖	XRD-79 ✓
✓AD-376828L 🌂	XRD-76✓
✓AD-367464. ※	XRD-106 <
AD-801404L	XRD-105-Volume 1
✓AD-367459 🕱	XRD-100✓

TRC

Subject: Declassification of Reports

✓ AD-367517 🔾 XRD-141 ✔ AD-366762**▶** XRD-84 AD-366760**✓** XRD-81 AD-366761 XRD-82 AD-367501 XRD-158-Volume 1 AD-367507L 🗸 XRD-152-Volume 4 ✓ AD-367495 🔏 XRD-184~ ✓AD-367485 ¥ XRD-129℃ AD-367484 X XRD-128 ✓ AD-367483 🔏 XRD-127℃ AD-367482**X** XRD-126► AD-367488 ► XRD-132 AD-367480 XRD-124~ AD-801409L**√** XRD-135 AD-367490 💢 XRD-136 × AD-367492 💢 XRD-137► AD-801411L 🗸 XRD-139 AD-367518 🗶 XRD-140 ✓ AD-367515 ✓ XRD-144 AD-367514 ✔ XRD-145 AD-367468 **X** XRD-110-Volume 2 ✓ AD-367513**√** XRD-146

XRD-162'

AD-367497**X**

Subject: Declassification of Reports

AD-801406L ✓ XRD-114.

In addition, all of the cited reports are now approved for public release; distribution statement "A" now applies.

Andith Jarrett

Chief, Technical Resource Center